

### ATTENTION!!!

BEFORE CLEANING PROCESSOR, YOU MUST FIRST--

-  
DRAIN SILVER LADEN FIXER INTO THE SILVER RECOVERY UNIT.  
THEN CLAMP OFF, DISCONNECT, OR BYPASS SILVER RECOVERY  
UNITS.

NO DEBRIS, CLEANING SOLUTIONS, OR RINSE WATER SHOULD BE PERMITTED TO ENTER  
SILVER RECOVERY UNIT.

AFTER CLEANING PROCESSOR, YOU

MUST --

UNCLAMP, RECONNECT OR UN-BYPASS SILVER  
RECOVERY UNITS.

IF THE PROCESSOR HAS BYPASS VALVES (EITHER OEM OR  
AFTERMARKET), PLEASE MAKE SURE THAT THEY ARE IN  
THE NORMAL POSITION WHEN THROUGH CLEANING THE  
PROCESSOR

FOLLOWING THESE INSTRUCTIONS WILL ENABLE THE SILVER RECOVERY  
EQUIPMENT TO FUNCTION AT PEAK EFFICIENCY AND TO RETURN THE  
MAXIMUM RECOVERED SILVER YIELD INCOME AVAILABLE TO THIS FACILITY.  
FAILURE TO COMPLY WITH THE ABOVE INSTRUCTIONS CAN RESULT IN  
CLEANING MATERIALS CLOGGING THE SILVER RECOVERY UNIT, AND WILL  
SEVERELY RESTRICT THE EFFICIENCY OF THE SILVER RECOVERY UNIT. THIS  
MAY CAUSE NON-COMPLIANCE WITH FEDERAL, STATE, AND LOCAL E.P.A.  
REGULATIONS.

NON-COMPLIANCE WITH THESE REGULATIONS CAN RESULT IN FINES OF UP  
TO \$5000.00 PER DAY AND CAN BE LEVIED AT BOTH THE FACILITY AND THE  
PROCESSOR SERVICE COMPANY.

CHECK SILVER RECOVERY UNITS WEEKLY TO ENSURE THEY'RE OPERATING.

PLEASE POST THIS NOTICE IN A CONSPICUOUS LOCATION NEAR PROCESSOR TO ENSURE COMPLIANCE.